



# Intel® SoC Watch for Windows\* OS 2.9

---

*Release Notes*

14 January 2019

## Version History

These are the main releases of Intel SoC Watch:

Date	Revision	Description
November, 2017	2.4	First release that aligns all command line parameters and output formats across all supported operating systems.
December, 2017	2.4.2	Update release, includes support for Intel platforms code named Apollo Lake (new stepping) and corrected console message order when using delayed start option.
February, 2018	2.5	Includes support for Intel platform code named Gemini Lake and other fixes.
April, 2018	2.6	Enhancements include new hot key Alt-S, new --log option, modified metric groupings, and improved support in gfx metrics.
May, 2018	2.6.1	Update release.
August 2018	2.7	Added average frequency report, new options (program-delay, disable-alts), new metric (pkg-pwr), new group names, support for Intel platform code named Whiskey Lake, Amber Lake, and Cherry Trail, fixed issues in ddr-bw, automation summary, and multiple pkg handling.
November, 2018	2.8	Added filter for acpi-dstate devices. Fixed error in ddr-bw reporting. Alt-S hotkey off by default.
January, 2019	2.9	Added trace file report grouping and informational messages.

## Intended Audience

Use this document if you use Intel SoC Watch to analyze power consumption on a Windows\* system.

## Customer Support

For technical support, including answers to questions not addressed in this product, visit the technical support forum, FAQs, and other support information at: <https://software.intel.com/en-us/intel-system-studio-support>.

# Contents:

---

<a href="#">1</a>	<a href="#">Introduction</a>	<a href="#">4</a>
<a href="#">2</a>	<a href="#">New in This Release</a>	<a href="#">5</a>
<a href="#">3</a>	<a href="#">System Requirements</a>	<a href="#">6</a>
<a href="#">4</a>	<a href="#">Where to Find the Release</a>	<a href="#">7</a>
<a href="#">5</a>	<a href="#">Installation Notes</a>	<a href="#">8</a>
<a href="#">6</a>	<a href="#">Fixed Issues</a>	<a href="#">9</a>
<a href="#">7</a>	<a href="#">Known Issues</a>	<a href="#">10</a>
<a href="#">8</a>	<a href="#">Related Documentation</a>	<a href="#">12</a>
<a href="#">9</a>	<a href="#">Release Content</a>	<a href="#">13</a>
<a href="#">10</a>	<a href="#">Acronyms and Terms</a>	<a href="#">14</a>
<a href="#">11</a>	<a href="#">Legal Information</a>	<a href="#">15</a>

## 1 Introduction

Intel® SoC Watch is the data collector for power-related data that helps identify issues on a platform that are preventing entry to power-saving states. The metrics it captures include system sleep states, CPU and GPU sleep states, processor frequencies, temperature data, and device sleep states among others. The collected data can be correlated and visualized over time using the Intel® VTune™ Amplifier.

This document provides system requirements, installation instructions, issues and limitations, and legal information.

To learn more about this product, see:

- New features listed in the [New in this Release](#) section below
- Reference documentation listed in the [Related Documentation](#) section below
- Installation instructions can be found at: [Installation Notes](#)

## 2 New in This Release

Release v2.9 includes the following:

- **Improved organization of reports in `_trace.csv` report.** All reports belonging to a feature are now grouped together.
- **Improved informational message.** Added CPU ID model/family/stepping values when reporting it as unknown.
- **Modified `-f hw-cpu-cstate` reports as follows:**
  - In Package C-state report, added following notes to make it clear that software cannot request to enter PC2 or PC3 states explicitly, these are used by hardware.
    - Note: PC2 is non-architectural state - software cannot request to go to PC2 explicitly. PC2 can be a transient state between PC0 and deeper pkgC states.
    - Note: PC3 is non-architectural state - software cannot request to go to PC3 explicitly.
  - In the Core C-state report, removed the C3 state for platforms that are not using it rather than always reporting 0.

## 3 System Requirements

### Supported Architectures and Terminology

Intel SoC Watch supports the following Intel microarchitecture and platform code names:

- Apollo Lake
- Gemini Lake
- Skylake
- Kaby Lake
- Coffee Lake
- Whiskey Lake
- Amber Lake

### Minimum System Requirements

This tool can be run on the Windows\* 8.1 and Windows 10 (desktop) 64-bit operating systems, with administrator permissions.

## 4 Where to Find the Release

Go to the [Intel® System Studio website](#) to get either an Evaluation (30-day trial release) license or a commercial license, and download the package from [Intel Registration Center](#).

## 5 Installation Notes

Intel SoC Watch for Windows\* OS is installed as part of Intel System Studio when downloaded to a Windows host system.

### Default Installation Folders

The default top-level installation folder for this product is:

```
C:\Program Files (x86)\Intel\SoCWatch
```

If you are installing on a system with a non-English language version of Windows OS, the name of the `Program Files` folder may be different. On Intel® 64 systems, the directory name is `Program Files (X86)` or the equivalent.

### Installing on a Remote Target

You can install Intel SoC Watch on a remote Windows system. Detailed instructions are available from <https://software.intel.com/en-us/socwatch-help-preparing-a-target-windows-system-for-energy-analysis>.

### Changing, Updating, and Removing the Product

If you want to add or remove components from an installation, open the Control Panel, select the Add or Remove Programs applet, select Intel System Studio, and click **Change**. To remove the product, select Intel SoC Watch and click **Remove**.

When installing an updated version of Intel SoC Watch, any previously installed version will automatically be removed.



## 6 Fixed Issues

Release v2.9 has a fix for the below issues.

- **Removed column with redundant data in trace file reports for features os-cpu-cstates, os-cpu-pstates.**
- **Intel® VTune™ Amplifier 2019 Update 2 no longer reports error during import if too many metrics are included in the .pwr file.** Previously, if the .pwr file being imported included too many metrics the following error was seen: *Error 0x4000002a (Database interface error) - Precompute error.*

## 7 Known Issues

This release contains the following known issues.

- **On platforms with HyperV enabled, the sum of the CPU C-state idle residencies will not match CPU P-state idle residency time.** The issue occurs because HyperV does not allow setting of a bit, resulting in incorrect core-level reporting of both C-state and P-states.
- **Feature pkg-pwr has incorrect table name and column headers.** They report "Average Rate and Total" and should say "Average Power and Energy." The column units correctly identify power in milli-Watts and energy in milli-Joules.
- **Package power reported incorrectly for systems with multiple packages.** The `-f pkg-pwr` feature will report an incorrect value for energy and power on systems with multiple packages.
- **Metrics report Unknown 0 and do not sum to total collection time when -m is not used and hibernation occurs.** Metrics with a snapshot default collection mode, such as CPU C-state, will show the *Unknown* state with 0 time and the remaining states will not sum to the total collection duration if the system entered hibernation during the collection and the `-m` option was not specified. The snapshot metrics are only collected at the start and end of a collection by default, but finding hibernation time requires samples taken throughout the collection - including `-m` will cause continuous sampling to occur for all metrics. When hibernation occurs, a message reporting time spent in hibernation appears at the beginning of the summary report. The *Unknown* state is then included for all appropriate metrics and the time in hibernation is included in that state. Refer to the Intel SoC Watch User's Guide *Options Quick Reference* section to learn which metrics have a snapshot collection mode by default.
- **Syntax errors in the command line may not report a visible error message.** If a collection did not run and you are not seeing any error message, add option `-d 2` to your command line to get more information.
- **Insufficient system resources error seen on occasion when collecting OS event trace metrics such as acpi-dstate.** The system error "*WARNING: Cannot enable provider in the trace file <etl filename>*" has been reported when collecting metrics that enable event trace logging. This error prevents ETL logging from being started and is usually caused by a background process consuming system resources. Use Task Manager to find and remove such processes then try the collection again.
- **Hyper-V and Virtualization-based Security (VBS) prevent some metrics from being collected.** Intel SoC Watch detects when Hyper-V and Virtualization-based Security is enabled on the platform, reports a warning message on the console and disables metrics that are blocked by these settings. When Hyper-V and VBS are enabled then `cpu-gpu-concurrency` cannot be collected.
- **Total DDR bandwidth does not include EDRAM.** On systems using EDRAM, the `ddr-bw` feature report may have a discrepancy between the total data read and writes and the total component requests. The Data Reads+Data Writes will be significantly higher than the total IA+GT+IO requests, because the EDRAM requests are not included.
- **Collection on Windows\* Server 2016 OS will result in failure to load the Intel SoC Watch driver if Secure Boot is enabled on the platform.** The workaround is to disable Secure Boot. The problem on Windows 10 client OS was resolved.
- **If a command window is closed (using either the X button or Alt-F4) while the socwatch process is running, or the Task Manager is used to kill the socwatch process, then the behavior of a**

**subsequent run of Intel SoC Watch becomes unknown.** The proper way to terminate Intel SoC Watch is using Ctrl-C. A collection driver may be left in an undefined state when Intel SoC Watch is abruptly terminated because there is no OS event to allow proper cleanup. This can cause the next Intel SoC Watch collection to result in anything from bad data to a system crash. If a driver is left running, it must be removed. You can reboot the system to clear a driver or use the following set of commands to check if the driver is running, stop it, and then delete it: `sc query socwatchdrv; sc stop socwatchdrv; sc delete socwatchdrv.`

- **OS-based CPU P-state report does not support platforms with > 64 logical processors.** The hardware-based P-state report is correct. The problem is in the OS event trace which provides state changes for only a partial set of logical processors when the platform is configured for more than 64 logical processors. When this situation occurs, a warning message is printed in the report indicating which processors have no OS P-state change events.
- **Issues on Intel platforms code named Apollo Lake and Gemini Lake:**
  - **Memory bandwidth and memory self-refresh metrics not available.** The following features are not supported: `ddr-bw`, `cpu-ddr-bw`, `cpu-ddr-mod0-bw`, `cpu-ddr-mod1-bw`, `disp-ddr-bw`, `isp-ddr-bw`, `gfx-ddr-bw`, `io-bw`, `all-approx-bw`, `dram-srr`.

## **8 Related Documentation**

The below documents are available with this release.

- Intel® SoC Watch for Windows\* OS User's Guide
- [Energy Analysis help](#)

## 9 Release Content

Intel® SoC Watch for Windows* OS User's Guide
Intel® SoC Watch for Windows* OS Release Notes
Intel® SoC Watch for Windows* OS executables

## 10 Acronyms and Terms

The following acronyms and terms are used in this document (arranged in alphabetic order):

Acronym/Term	Description
SoC	System on Chip

## 11 Legal Information

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting [www.intel.com/design/literature.htm](http://www.intel.com/design/literature.htm).

This product includes software developed by the OpenSSL Project for use in the OpenSSL Toolkit (<http://www.openssl.org/>).

Intel, Intel Atom, Intel Core, the Intel logo, and VTune Amplifier are trademarks of Intel Corporation in the U.S. and/or other countries.

Optimization Notice: Intel's compilers may or may not optimize to the same degree for non-Intel microprocessors for optimizations that are not unique to Intel microprocessors. These optimizations include SSE2, SSE3, and SSSE3 instruction sets and other optimizations. Intel does not guarantee the availability, functionality, or effectiveness of any optimization on microprocessors not manufactured by Intel. Microprocessor-dependent optimizations in this product are intended for use with Intel microprocessors. Certain optimizations not specific to Intel microarchitecture are reserved for Intel microprocessors. Please refer to the applicable product User and Reference Guides for more information regarding the specific instruction sets covered by this notice.

Notice Revision #20110804

\*Other names and brands may be claimed as the property of others.

Microsoft, Windows, and the Windows logo are trademarks, or registered trademarks of Microsoft Corporation in the United States and/or other countries.

### Copyright 2013 - 2019 Intel Corporation.

This software and the related documents are Intel copyrighted materials, and your use of them is governed by the express license under which they were provided to you (**License**). Unless the License provides otherwise, you may not use, modify, copy, publish, distribute, disclose or transmit this software or the related documents without Intel's prior written permission.

***Intel® SoC Watch for Windows\* OS 2.9***

This software and the related documents are provided as is, with no express or implied warranties, other than those that are expressly stated in the License.